



Barva: ■ Oranžová

Wiring aid WINSTA® MIDI

The wiring aid from the WINSTA® MIDI product line guarantees you the greatest possible flexibility in electrical installation. With WAGO, you can enjoy the advantages of a large selection of expansions for the WINSTA® product line. WINSTA® MIDI with Push-in CAGE CLAMP® spring pressure connection technology is found in a broad range of individual products you can use for quick, easy and maximally flexible installation.

WINSTA® MIDI solutions for your electrical installation – protected against mismatching and maintenance-free

The WINSTA® Pluggable Connection System is ideally tailored to the strict requirements of building installation. It makes electrical installation pluggable, and consequently faster, even more reliable, and error-free. Use of this pre-assembled system decreases time spent on assembly and errors during installation at the construction site. Enjoy the benefits of the pluggable version of our maintenance-free spring pressure connection technology too! Plan your installation with with protection against mismatching from WAGO.

- pre-assembled versions
- rapid, structured electrical installation

Údaje o materiálu

Upozornění k údajům o materiálu

[Zde najdete informace o specifikaci materiálu](#)

Barva	Oranžová
Izolační materiál	Polyamid (PA 66)
Třída hořlavosti podle UL94	V0
Požární zatížení	0,839 MJ
Hmotnost	28 g

Požadavky na prostředí

Teplota pro zpracování	-5 ... +40 °C
Trvalá provozní teplota	-35 ... +85 °C
Upozornění k trvalé provozní teplotě	Izolační části pro teploty ≤ 105 °C

Obchodní údaje

Product Group	20 (Winsta)
eCl@ss 10.0	27-44-06-92
eCl@ss 9.0	27-44-06-92
ETIM 8.0	EC002863
ETIM 7.0	EC002863
PU (SPU)	20 (1) ks
Druh balení	Box
Země původu	DE
GTIN	4017332819787
Číslo celního tarifu	85369010000

Environmental Product Compliance

RoHS Compliance Status	Compliant, No Exemption
------------------------	-------------------------

Ke stažení

Environmental Product Compliance

Compliance Search

Environmental Product Compliance 770-100



CAD/CAE-Data

CAE data

WSCAD Universe 770-100



Pokyny k instalaci

Aplikace



Odstraňte plášť.




Zaštipněte konce vodičů (3pól.).




Odstraňte vnější izolaci, vložte kabel do pomůcky pro zapojování a uspořádejte jednotlivé vodiče podle značení, počínaje neutrálním vodičem.




Zaštipněte konce vodičů (5pól.).



Konce vodičů odizolujte v délce 9 mm (viz potisk).



Zapojený konektor vsadte do pouzdra pro odlehčení tahu (3pól.).



Zapojený konektor vsadte do pouzdra pro odlehčení tahu (5pól.).